HIRE THE EYE OF THE TIGER 1-800-62-TIGER

www.tigerhomeinspection.com

AN AGREEMENT

Congratulations on your expected purchase! You have made a wise decision in having your prospective home inspected. Our inspector will present you with an objective, general evaluation of the home, consistent with the professional practices and standards of the home inspection industry. To understand the report, you should read the entire document including all pre-printed and hand-written materials, and please read the important information section on each page. Each of these areas provides critical information. Please note that this inspection is limited in time and scope and not all repairs or defects may be discoverable at the time of this inspection.

Our inspectors present observations that are based on the visual examination of accessible areas of the property on the day of inspection. There is no destructive testing, probing or dismantling of any components. We cannot predict the future life expectancy or sudden failure of any component. This report is not an engineering study, or a substitute for an insurance policy, Home Warranty package (ask your broker or Tiger representative about a Home Warranty), or a Manufacturer's Warranty.

You can certainly understand that we cannot see through walls, remove insulation or suspended ceiling tiles, nor enter crawl spaces that are less than 3 feet. We cannot enter attics that are not specifically designed for safe pass through. This report does not warranty the absence of wood-destroying insects. It is, however, a visual, non-destructive investigation for indications of previous or ongoing activity in readily accessible areas. Future repairs or renovations may reveal defects or wood-destroying insect activity that were not discoverable during the inspection. Tiger is not responsible for damage which is concealed or not readily accessible at the time of the inspection. If wood-destroying insect activity is discovered during the interior or exterior inspection, that activity will be documented on the report.

No evaluation has been made regarding air, soil, lead, water, waste disposal or sewage systems, asbestos, urea formaldehyde, lead paint, molds, radon, piping outside the foundation, natural or propane gas fittings or regulations, swimming pools, wood stoves, telephone systems, alarm systems or out-buildings unless otherwise noted. This report does not include the detection of rodents or general pests. We do not make an assessment of compliance with building codes. Tiger is not responsible for pointing out repairs needed to bring the home in compliance with current building codes or other regulations, and we do not report on whether the property may be lawfully used for rental, business or any other purpose. _____Intl.

Please be aware that only those components specifically mentioned in this report have been inspected and those components not included are not part of this report. We do not make any representation, implied or otherwise, concerning the condition of non-inspected areas. You should evaluate concerns about specific components with a qualified specialist and act upon any comments or recommendations before continuing with your purchase. It is important that you further evaluate those areas not included in this report as well as those items recorded as B, C, or NR prior to continuing on with your purchase. Tiger is not responsible for repairs on any component rated B, C, or NR. This report will not necessarily reveal all defects on the property and should not be used for negotiations._____intl.

In the event that you believe the condition of a component has not been accurately disclosed or that a particular component has been omitted from the report, it is your responsibility to notify Tiger and permit us to investigate and evaluate the situation before you make any corrective action. It is agreed that Tiger is not responsible for costs associated with repairs made prior to Tiger's investigation.

If you or anybody on your behalf chooses to initiate any type of civil action or law suit against Tiger or its inspector as a result of this inspection, in which Tiger prevails, you agree to indemnify and reimburse Tiger for its attorney fees, costs and expenses. This inspection is for your use and benefit only it may not be assigned or relied upon by any other party without written consent from Tiger. You also agree to indemnify and hold harmless Tiger for any subrogation action filed by an insurance company or any other third party as a result of this inspection.

Tiger reserves the right to retain the Inspection Report if the fee is not paid for at the time of the inspection. If the Inspector is requested to go back to the property after the inspection to check a component that was turned off, not accessible, or rated NR, there will be a \$125.00 charge. An additional charge of \$125.00 will apply to all requests for typewritten reports.

Now that you have read and understand our Agreement and wish to proceed please sign below.

		\$ 505		
Client Signature		Total Amount Due	1 1	
X		KUINDAFILL	1 smondel	9/2/08
Print Name	Date	Inspector	License# 68	Date
PROPERTY INFORMATION:				
57 RUZLAMS ST		BosTON	ma	
Street		Town	State	Zip

The above authorizes Tiger Home Inspection to conduct a Home Inspection on the referenced property.



HIRE THE EYE OF THE TIGER

GENERAL INFORMATION PAGE

Address of Property 50 NUTLAM ST	Date of Inspection 9/20/08
Busron ma	Start Time 3130 Finish Time 5100
Individuals Present Regard Owner Acen	
Weather Conditions: Current Day Cocc Previous Day Sumulcocc	
Current Temp. 619 Ground Conditions Dry	
Services Provided: Amount:	
Inspection Type Much 1600 \$ 535	
Wood Destroying Insect Inspection N/C	
Radon	
Water Quantity	
Water Quality	
Title 5 Inspection	
Other	
Total Amount Due: \$ 535	
I, the undersigned, acknowledge the receipt of the following documents;	
An Agreement Page General Information Page Tiger Home Inspection Report Tiger Home Inspection Insect Disclosure Page State Required Questions (a)-(k) Wood Destroying Insect Report Form NPMA-33 General Information Page	
200 OWIN Delimitions and Standards of Fractice	
Client Signature	
Print Name Date	Email

HIRE THE EYE OF THE TIGER

1

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

EXTERIOR

		A	В	С	NR	Δ	
1.	Roof style Flat (PITCHED	d				0	COUBRER MEMBRANE ON PITCHES
	Surface type Puss Scare (TOT COTICE)			0		(2)	POUT TIME SEAMS AT ASOMALT DAMAGED
	How viewed SCANDING OR						LIFTING LUBBEN CLUTKED DUMPERO
	Vent Stack: present / not present						SLADE TAPIGRAVE CONSULT
2.	Exterior of Chimney: See Comment E			a		0	WITH CONTERITOR FOR SEADIN
	(Flue Liner not included)						@ Coose masonly Brick ATCAS
	type Brac clean out						TOPALT
	cricket flashing/sealer						•
3.	Siding: Type Brice			a		à	3 Lovce MASONA, BrigGATCAS
4.	Trim: eaves/soffits/fascia/corner board, etc.			Ø		Ø	DAMAGES SPALLING LINTELS TEADIT
5.	Exposed gutters and downspouts:						@ SOFT NETTO DAMAGED TEIM ATTAS
	Type recal			0		0	
6.	Perimeter drainage and grading	D	0				
7.	Basement windows	4					GUETERS TEPAIT
8.	Window wells				4		Blokeschertenser
9.	Exterior faucet				Q		
10.	Electric service entry				Z		
	☐ weather head/drip loop ☐ meter box		÷.				@ GFE NOT WORKING SERAIT
	✓ underground ☐ service amp						
-11.	Exterior outlets GFCI			0		0	
12.	Exterior lighting	Ø					QUA STOR MASOLINA, STOR AND
13.	Oil Fill / Vent						Brick Areas FENALT
	Walkways Type Common	Ø					
15.	Driveway Type Stole 0100		A	0		a	
16.	Railings/Decks/Porches/Stairs/Balconies						(B) LUCK MASOLRI AT STAIL B CA)
	Front Type KAN Material Stoke		0			0	MISSING HANDRAILS SCHOLL
	Prear Type Material MCNC			Ø		Ø	@ DAMAGES STAIRS COOP MOTSSING
	side Type Material				Ø		HIRYOURIES EVEN
	Patios Type				X		
18.	Retaining Walls within 10ft of structure				D		

IMPORTANT INFORMATION PLEASE READ:

A. Manufacturers of asphalt shingles, on average, provide a twenty year warranty. This should not be confused with the actual roof life. Actual roof life cannot be predicted due to many variables. B. It is advised that reserves be set aside for repairs or eventual replacement. It is suggested that no more than two layers of roofing lie on the roof. C. Check flashing yearly. D. To prevent water damage to roof, sheathing, walls, ceilings and structural members, gutters and down spouts must be kept clean and clear of debris. It is suggested that you check periodically to ensure all is working well. E. Local regulations in some communities require the presence of a flue liner when using certain fuels. Consult your local authorities. F. Window wells should be cleaned annually. G. Exterior faucets should be drained during the colder months to prevent freezing. H. Driveway should be sealed to extend its life. I. The underside of decks and porches not accessible at the time of this inspection should be made accessible to check for damage, rot, infestation and construction methods. J. You should verify the roof's age through the broker, owner, or contractor. Also see page 8, Comment D. K. Wood contacting the ground is conducive to wood-destroying activity. Therefore it should be maintained or removed.



HIRE THE EYE OF THE TIGER

2

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

GAL	KAC	IL A	ND	BA:	SEIVI	EN	

		-	_		Λ	
☐ Garage: Type	A	В	С	NR	Δ	
1. Foundation: Type					Ø	
2. Floor: Type/					Г	
Wall/Siding/Trim: Type			ā	Z	ā	
4. Sill:		ā	ā	75	ā	
5. Automatic door opener/safety control		0	7	0	1	
6. Garage Door	0	0	75		10	
□ locks □ panels □ rollers	-	7	_	_	1	
springs windows track						
7. Electrical GFØI						
8. Fume barrier	7	7	Z			
9. Man door	7	X		ם כ	15	
10. Window	7		7			
11. Walls/Ceiling Type	3		00			
12. Roof: Style Surface	7					
13. How viewed	4	ч	ч	ч		
Basement:						
1. Foundation: Type Mas Bricic						
2. Floor: Type			000	区区区		\
3. Crawl area			1	1		\
			_	9		+
InsulationDepth	-					
□ ventilation □ vapor barrier						
How viewed	-					
4. Windows 5. Load bearing girders: Type 6. Support columns: Type 7. Sill: Type	4					
5. Load bearing girders: Type			4	DA		SECUTED BELOW BASCHERT
6. Support columns: Type						15 A FINISHED UNIT W
7. 0111. 1900				D		
8. Subfloor: InsulationDepth			000000	D		STRUCTURE
9. Joists: Type			4	4		- Muelli C
10. Bridging			Ч	Ø		/
11. Wall framing: Type						
(Liner not included) Clean out	d				ш	1
13. Bulkhead/walkout			0			
wood door/slider metal			0		a	(3) DAMAGED MASUNG, CMU
14. Water penetration and dampness						UNITS DOMAGED TOUT DEAS TEADLY
See Notes F and I.						CIDECT CIDITIAGED 1001 1016172 164171
Evidence noted at time of	-					Secure FANO I
inspection (See Comment H)				-		200000
Water stains: Location Efflorescence: Location	75	~				Below
		-0.7		7.4		
Sump pump Yes No Del	numi	diffe	r _	Yes	5	☑ No
French drain Yes No						

IMPORTANT INFORMATION PLEASE READ:

A. Fume barriers, firegrade sheetrock, and fire doors are required in most new construction. For safety, if your attached garage does not have these features you should consider adding them. B. Minor cracks in concrete walls and floors represent normal shrinkage. To reduce possibility of any water penetration they can be filled with hydraulic cement. C. Cracks that are offset or "V" shaped are signs of differential settlement. This inspection cannot determine if movement is continuous - consult owner or professional for history. D. Examination of structural members, walls, floors, ceilings, wiring, piping, etc., cannot be conducted. These areas are partially finished, rendering these items inaccessible. No destructive probing or removal of permanent or non-permanent partition or tiles is performed. E. Lumber, trees and adjustable columns are subject to shrinkage and deterioration; while they are acceptable under most circumstances, cement filled steel lally columns are preferable. F. Efflorescence is the white powdery substance often evident on concrete walls and floors. It is usually an indication that dampness or water penetration has occurred at some time. G. It has been noted that proper ventilation should be maintained to minimize deterioration of structural members caused by a variety of sources. H. The sump pump discharge lines should be checked regularly. Sump discharge lines should extend approx. 15 ft. from the house. I. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any concerns.



HIRE THE EYE OF THE TIGER

3

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

PLUMBING SYSTEM

	Α	В	С	NR	Δ	of
Supply I munic. D pvt How verified 100	ENT					0'
Waste munic. pvt How verified	EN					
Waste / Supply for reference only.						
See note C & F.						
Visual condition of accessible feed lines						t
and connectors within structure		a			0	ORUSTON ST MAIN WATER
☑ copper ☐ lead ☐ brass						SHUJOEE EEBPLE
galvanized plastic other						
Visual condition of accessible waste						
lines/connections within structure				d) BASEMENT 15 A FINISHED
copper Cast iron lead						LIVING ASCA W ALLESS TO
☐ galvanized ☐ plastic						TURSET OF WASK CONNECTIONS
other						
3. Main vent stack				V		
4. Accessible well equipment/				0		
5. Laundry tub				NAA		
6. Washer/dryer connections				1.		ч
Present Not Present						
See Note I.						
7. Water heater		0			0	(1) 1997 TANK SICHTE B
manuf. Run fyel Frc gal 80						Below one TORKIL SCHULLING
safety controls tankless						Four units
Pressure & temperature relief valve						
☐ Vacuum breaker						
Thimble						
8. Interior sewer ejector pump				1		
ADDITIONAL COMMENTS					lease record	
ADDITIONAL COMMENTS:		-				
					-	
	-			-		
			-			
						,
	-					

IMPORTANT INFORMATION PLEASE READ:

A. Due to the age of the house, not all fixtures may meet current standards; therefore, upgrades to the plumbing, waste, supply and venting systems may be needed when renovating or repairing. B. Manufacturers' warranties for hot water heaters vary from manufacturer to manufacturer; this should not be confused with the actual life expectancy which could be more or less. Please refer to the warranty for the extent and terms if any. C. The type of sewage disposal system as noted above is determined by information provided by either seller, broker or client. It is not a determination of its actual type, design or condition. An optional inspection report is available to offer an opinion of the system's type, effectiveness and condition. D. No conclusions as to quality and quantity of the water supply is implied. It is recommended that you have both a quality and quantity test performed. E. Depending on your individual needs, a tankless unit may not provide you with sufficient hot water. To increase quantity and efficiency you may wish to consider a booster tank or separate water heater. F. Main water shut offs, individual fixture shut offs, and other valves are not tested. G. Follow manufacturer's recommendations for all water conditioning equipment. Failure to provide adequate maintenance can lead to equipment malfunction and affect water quality. H. An indirectly fired hot water storage tank is heated by the central heating system. I. For Identification purposes only, no determination of proper operation or termination.



HIRE THE EYE OF THE TIGER

4

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

ELECTRIC SYSTEM

	☐ Supply 120V ☐ 120/240V	Α	В	С	NR	Δ	of
1	Accessible wiring	0					1 "-
1.	Copper Romex Knob & Tube	-	_	_	_	7	
-							
	□ Aluminum □ BX	_	_	_	_		
2.	Service panel box	Ø					
	Readily Accessible Yes No Main disconnect fused at AMP						
	Main disconnect fused at AMP						
	Location 3ASC.						
	☐ Cu/Al						
	Service wire 310 Breaker D Fuse						
	Sub panel(s) 6 Location UNITS						
2	Ground Terminal Bars	1					
٥.	Bonded to the panel	~		_	_	-	
		d					
4.	Electrical Grounding/Bonding	D					
	Within 5 ft of water main						
-	Both sides of water meter		1				
	Grounding Rod						
5.	GFCI O	00			N D		
6.	AFCI 3 leach to pance	0			9		
7.	Over current device/s in off position						
	Yes No						
	Identify						Service
8.	Junction box covers	Ø					
9.	Switch and outlet covers	0					15e10w
10.	Smoke/fire detectors SEE NOTE: C		_				Ticosphalit (1970) my amough
10.	omoronio detectoro del rio el con		-			-	
ADI	DITIONAL COMMENTS:				-		
-							

IMPORTANT INFORMATION PLEASE READ:

A. The current main fuse capacity is not always an indication of its maximum capacity. Consult with an electrician. B. The decision to upgrade electric service can be influenced by client need, local regulations and mortgage lending institutions. Furnishing and living conditions allow for only random testing of electrical outlets. Light switches are not included. C. Smoke detectors should be installed and approved by the local fire department prior to purchase. Tiger makes no representation as to the operability or installation of smoke detectors. D. Once or twice a year flip circuit breakers off and on to maintain good mechanical contact. GFI breaker or outlets should be tested monthly. E. Ground Fault Circuit Interrupter outlets or breakers are advised whenever the user will come in contact with water.



HIRE THE EYE OF THE TIGER

5

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
 - △: Further consultation with a contractor is advised.

						and the second s
☐ Oil	Α	В	С	NR	Δ	Qof
1. Thermostats: Location Fur Lucial	Z		O	0		Secure A.DE
2. Fire grade sheetrock	Z					
3. Emergency shut off: present / lot present						1300w
Exposed flue and damper from		}				
the Heat Plant.						
5. Burner/Gun				₽		(1) 1997 SUSTEM TO SCOULE TAGS
6. Fire box liner				2		DIM DEBTIS DT BULNER WE DEA
7. Boiler Type Scam		4	0		0	PUSC AT SIGHT GIASS ATA
⊿′ PSI	İ					CONSULT WITH CONTRACTOR FOR
sight glass low water cut off						Scruce AND CLEANING UIBRIATION
exp. tank water level 314						SULLY DE CESON NIMA
□ auto feed □ press. relief valve						IN ALL UNITS
back flow preventer						
8. Circulator pump #						
9. Zone valve #				Z		
10. Pipes						
🔲 Black Iron 😭 Copper 🖵 Plastic				£ :		
Other						
11. Furnace Type				Z		
Heat exchanger, Important See Note C				_		
12. Circulator fan				X		
13. Filter						
14. Duct work (in basement)				Z		
🗖 galv. steel 🗖 alum. 🗖 flexi duct 🗖 other						
15. Electric baseboard heat				Z		
16. Space Heaters Location				MAN I		
17. Fuel tank						
propane fill and vent stacks						
oil level 🔲 emergency shut offs						
18. Cooling system (Ducted systems only)				900		·
19. Compressor				Ф		· · · · · · · · · · · · · · · · · · ·
20. Evaporator unit/				$\mathbf{\Psi}$		
21. Service line				ф		
insulation			,	\perp	_	
22. Condensate drain/pan/float switch/pump				#		<u> </u>
23. Temp. at service line/						
24. Temp. at air intake-outlet/						
25. Electric disconnect		0				
26. Compressor slab					Ш	

IMPORTANT INFORMATION PLEASE READ:

A. This report indicates the condition of the heat plant from a dealer or contractor which should include annual servicing, adjustments, efficiency testing, warranty and emergency service. B. In the event that the unit is a coal conversion furnace/boiler, it is at the end of its economic usefulness. Expect repairs or replacement. C. To determine the condition of the heat exchanger in forced Hot Air units, major disassembly by a heating technician is required. This report does not represent the condition of the heat exchanger and we recommend that you have this evaluated. Defects in the heat exchanger may require replacement of the entire furnace. D. Relief valves, valves, gauges, switches, and other safety devices cannot be tested. They are listed on the report to denote that they were observed in place on the system. E. Check with the local community for regulations regarding discontinued oil tanks. F. Suspect material noted at property. This material should be further evaluated by a qualified specialist. G. All material must be kept clear of contact with electric baseboard for safety. Electric thermostats have a limited life expectancy. H Radiant heat slabs and ceilings are not accessible. I. Air conditioning units and heat pumps cannot be operated out of season as this could cause damage. J. Most compressors and evaporators are sealed units which are not accessible. The average life expectancy is 5-10 years. K. Annual servicing of the A/C heat pump system by a licensed technician is advised. L. Propane or gas piping not included in this report. Consult licensed contractor.



HIRE THE EYE OF THE TIGER

C



Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

KITCHEN

	Α	В	С	NR	Δ	-
1. Sink Water flow HW Temp \6 °F			Ø		Ø	OLOUSE HANDLES MYSSING FILTER
2. Counters Top			2	0		21001
3. Cabinets	_		0			
	_				Z	@3 DAMAGES ATERS NUTED
4. Walls	1	100000		_		
5. Ceilings						TCARIT
6. Windows		_		2		
7. Floor	,					
8. Electric Outlets GFCI	Ø					
9. Heat Source Temp°F				1		
10. Baseboard/Radiator/Diffuser/Toe Kick	1			Ø		
APPLIANCES W	/king	Not Wkin	ıq	NR	Δ	_
	1		Ĭ			Secure H Below
1. Stove Top and Oven Gas Elect	-			0	0	0
2. Ventilator	1	1			J	15 elow
3. Dishwasher	_	0		Q'	u	
4. Disposal				A	u	
INTERIOR ACCESSORIES	Α	В	С	NR	·	
1. Door:	2				П	
☑ rear	a	ō	ō	2		
side				1		
2. Sliding door				以内区		
3. Fireplace				Ø		
(Flue liner not included) see note 1						
Solid Fuel Stove: present / not present						
see note: K Thimble		_				
4. Stairway/Railings (Basement)				2		
Stairway/Railings (Interior)	X					
5. Halls	D				u	
6. Skylight Location	u	u	U	X	u	
ADDITIONAL COMMENTS:						

IMPORTANT INFORMATION PLEASE READ:

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Fireplaces are inspected visually only; test fires are not started as a part of this inspection. C. Check with current owner for location and condition of any and all screens and storm windows. D. Fog or condensation between insulated glass is an indication of a broken thermal seal. However, due to the nature of the defect this situation may not always be detected. E. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Damage beyond the tile surface is not accessible (NR) and further evaluation is suggested. Poor grouting will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members. F. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. G. Cosmetic defects such as: blemishes, worn carpets, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. H. Unless otherwise noted, all appliances are working on the day of the inspection. Tiger Home Inspection, Inc. does not represent a guarantee or warranty of the continuous operation of the appliances. Self-cleaning mechanism, timers, clocks, thermostats, microwave ovens, clothes washing machines and dryers, and cosmetic blemishes are not part of this inspection report. I. Clean all grease vents and filters on a regular basis to prevent failure. J. Manufactured / pre-fab gas log units are not inspected as fireplaces but are considered space heaters. K. Solid fuel stoves are not inspected. If a solid fuel stove is present obtain a permit from the local building inspector or fire marshal prior to purchase. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions ca



APARTMENT

TIGER HOME INSPECTION INC.®

HIRE THE EYE OF THE TIGER





Our rating system is as follows:

- Indicates item is functioning as originally intended.
- This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- Not inspected, not readily accessible or not present. No rating.
- A: Further consultation with a contractor is advised.

	Α	В	С	NR	Δ	
1. Electric Service						
Unit disconnect 175 AMP	Ø					
Location DINING	\cup					
2. Water Heater Type				2		
Size Manuf.			_		_	
Thimble						3 LOOK HANDAAICS FORIT
Staircase and handrail		(2)			a	
4. Door primary	ă		10000	0.711.67		
secondary						
				\alpha		3 LEDK DT SILK RENDIT
5. Bath sink HW Temp 101 °F	0	0000000000000	0000		2	
toilet FLR			Z	ood	DEBORDE	CIAW FOUT TUB LOOSE LEAKING
	ä	7	4	3		PIPE CONNECTIONS TOPPIT
- 1/2 - 10 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	ă	ă	O	ō	ŏ	
□ c ✓ window	ā	Z		ā	Ø	WATER DAMAGE AT WALL CEITING
Master Wall Type Wall Type			2		Ø	CELMOON DICKS REPORT
floor Type	2					
door	Z		COONCO	DODODNÀ		
GEDelectric/fan	4	4		4		to their source.
heat source Temp°F baseboard/radiator/diffuser		H	1	1		
1		10000		-	_	
G. Room Type Wallace	ď			000	9	@ WATER DIAMAGE AT CEITING FERALT
windows	3	9	O	7	20	
Walls Type Con Cultural Type	DA	7	7	H		
floor Type www		ā	0000		9	DOWNERD KLOOL BLEDZ KVDIZ
door			ā	2		
electric outlets 3\\	N					LEDGE AT DADIATOR TENDET
heat source Temp 32 °F.	MO				0	C 612/2 421 4642100 46 (12)
baseboard/adiator/diffusers			0		Q	
7. Room	N		П	0	П	
Type want oat	Z					
windows	N	00000000			0000	1 DAMAGO FIGHT ATERS SCHALT
walls Type \(\omega_{\infty}\infty\)	V		00			O Bringer Alde 14, Car of the
floor Type (Luc)			U			
door electric outlets		4			4	
heat source Temp°F.			H	00	1	LCAK AT MADIATOR PENALT
baseboard/radiator/diffusers	N			7	000	
8. Room		_				
ceiling Type	2					
windows	3	ووووووووو	1	1	B	
walls Type	<u>-</u>	7	ă	ä	6	
☐ floor Type		0	V	<u>a</u> /	ā	
door			D			
electric outletsX				A		
heat source Temp °F.				D		
■ baseboard/radiator/diffusers		L				

IMPORTANT INFORMATION PLEASE READ:

A. The decision to upgrade electric service can be influenced by client need, local regulations and mortgage lending institutions. B. Once or twice a year flip the circuit breakers on and off to maintain good mechanical connections. C. Manufacturers' warranties for hot water heaters vary from manufacturer to manufacturer; this should not be confused with actual life expectancy which could be more or less. D. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. E. Depending on your individual needs, a tankless unit may not provide you with sufficient hot water. To increase quantity and efficiency you may wish to consider a booster tank or separate hot water heater. F. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. G. Check with the current owner for the location and condition of all screens and storm windows. H. Due to the nature of the deficiency, insulated windows and skylights may have broken thermal seals that may not be detected. I. We recommend all structures built prior to 1978 be tested for lead paint.

J. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Re-grouting of these cracks is a maintenance responsibility. Lack of maintenance will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members around tubs and showers. Plaster or sheetrock behind tile is not accessible. K. Cosmetic defects such as worn carpets, cracked floor tiles, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any con



HIRE THE EYE OF THE TIGER

6



Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

VI	T	\sim	ш	AI
KI		U	п	IN

	Α	В	С	NR	Λ	
6000						of
1. Sink Water flow (CC) HW Temp (16°F)	1					
2. Counters Top	Ø					
3. Cabinets	Ø					
4. Walls	d					
5. Ceilings	12					
6. Windows	1			0	6	
7. Floor						
8. Electric Outlets GFCI	d					
		0	0	D	_	
9. Heat Source Temp°F				_		
10. Baseboard/Radiator/Diffuser/Toe Kick						
	ı	Not	ı			
APPLIANCES	/king	Wkin	g	NR	Δ	
1. Stove Top and Oven Gas CElect	Q					SPEWERM
2. Ventilator	d					Secure H Below
3. Dishwasher				Ø		
4. Disposal						
INTERIOR ACCESSORIES	Α	В	С	NR	Δ	
1. Door: 🚅 main	D					
🗖 rear				Z,		
side				Z,		
2. Sliding door				A		
3. Fireplace				d		
(Flue liner not included) see note J						
Solid Fuel Stove: present / not present						
see note: K Thimble				1		
4. Stairway/Railings (Basement)		0		DO		
Stairway/Railings (Interior)			ם כ		7	
5. Halls			7	L	7	
6. Skylight Location	_		7			
ADDITIONAL COMMENTS:						

IMPORTANT INFORMATION PLEASE READ:

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Fireplaces are inspected visually only; test fires are not started as a part of this inspection. C. Check with current owner for location and condition of any and all screens and storm windows. D. Fog or condensation between insulated glass is an indication of a broken thermal seal. However, due to the nature of the defect this situation may not always be detected. E. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Damage beyond the tile surface is not accessible (NR) and further evaluation is suggested. Poor grouting will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members. F. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. G. Cosmetic defects such as: blemishes, worn carpets, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. H. Unless otherwise noted, all appliances are working on the day of the inspection. Tiger Home Inspection, Inc. does not represent a guarantee or warranty of the continuous operation of the appliances. Self-cleaning mechanism, timers, clocks, thermostats, microwave ovens, clothes washing machines and dryers, and cosmetic blemishes are not part of this inspection report. I. Clean all grease vents and filters on a regular basis to prevent failure. J. Manufactured / pre-fab gas log units are not inspected as fireplaces but are considered space heaters. K. Solid fuel stoves are not inspected. If a solid fuel stove is present obtain a permit from the local building inspector or fire marshal prior to purchase. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions ca



APARTMENT

TIGER HOME INSPECTION INC.®

HIRE THE EYE OF THE TIGER



Our rating system is as follows:

- Indicates item is functioning as originally intended.
- This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- Not inspected, not readily accessible or not present. No rating,
- A: Further consultation with a contractor is advised.

	Α	В	С	NR	Δ	
1. Electric Service						
Unit disconnect AMP	12					
2. Water Heater Type				2		
Size Manuf		_	_	_	-	
Thimble						
Staircase and handrail						
4. Door primary				D		
secondary	_	0	0	A		
5. Bath sink HW Temp°F	片	1	A	7	DOO	BLECK DT SINK TUB SHOWET HANDLES
FLR. 🔼 tub/shower		ä	GWN A	0	d	TEMPLE MUT WATER SHUT OFF
Tile/fiberglass etc			12	2	DAD	
Geiling Type Control Type Window		7			7	WOTER DOMAGE BY WALL CENTRE WILDOW
Master wall Type Cu Schisolar	Z		Z	ō		ALEY? EVOIL
door Type	4	0000000000000		00000000000000000000000000000000000000		
GFVelectric/fan	1 CX	ä	ä	J.		to year source
heat source Temp F				Z		
baseboard/radiator/diffuser 6. Room						
Classifica Type Lyal Lanco	RAMONOOOR	000000000		0000000		(6 WATER DOMAGE AT WALL CENTING
windows Type COURDS	ā	ā	ā	ā	DA	WORNIN (290MAG SASIA WORNINGS
walls Type CASC(VOIS)			A			- Michael Charl
□ door		ä	5	Z		
electric outlets	4					
baseboard/radiator/diffusers		H	H			
7 Boom OFFICE		S 10 7 6				
Li ceiling Type (2001)	3			000		
windows	4					
windows		000000000	000000000		000	DAMAGES FOOT OFERS
u door		ō	ō	ā	ŏ	
electric outlets				000		IN HAST TO DADIATION PROPERTY WA
heat source Temp F. baseboard/rediator/diffusers	Z	d	9	ä	ă	
8. Room (5 C)						@ WATER DAMAGE AT WALL CLITICA ATTO
ceiling Type walker) windows	NO N	Z				@ Mister Warrange to tooks to tenting Mills
walls Type walls Type was floor Type		Z	1	H		Daniela Con Con
floor Type www			000000000	000		DAMAGES FROM MAIN
door	2					
electric outlets	DECE	70	7		3	
baseboard/radiator/diffusers						

IMPORTANT INFORMATION PLEASE READ:

A. The decision to upgrade electric service can be influenced by client need, local regulations and mortgage lending institutions. B. Once or twice a year flip the circuit breakers on and off to maintain good mechanical connections. C. Manufacturers' warranties for hot water heaters vary from manufacturer to manufacturer; this should not be confused with actual life expectancy which could be more or less. D. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. E. Depending on your individual needs, a tankless unit may not provide you with sufficient hot water. To increase quantity and efficiency you may wish to consider a booster tank or separate hot water heater. F. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. G. Check with the current owner for the location and condition of all screens and storm windows. H. Due to the nature of the deficiency, insulated windows and skylights may have broken thermal seals that may not be detected. I. We recommend all structures built prior to 1978 be tested for lead paint. J. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Re-grouting of these cracks is a maintenance responsibility. Lack of maintenance will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members around tubs and showers. Plaster or sheetrock behind tile is not accessible. K. Cosmetic defects such as worn carpets, cracked floor tiles, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration away to always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any conc



HIRE THE EYE OF THE TIGER

6



Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

\mathbf{Z}	T/		NI
ΚI	11	U	IA

	Α	В	С	NR	Δ	of
1. Sink Water flow 600 HW Temp 16°F			Z		Ø	QUEBIC BY SINK TOMPIC
2. Counters Top	Ø					
3. Cabinets	Ø					
4. Walls	d					
5. Ceilings	Ø					
6. Windows				Ø		
7. Floor	D					
8. Electric Outlets GFCI	Ø					
9. Heat Source Temp°F				Ø		
				Ø		
		Mad				
APPLIANCES W	king	Not Wkin	g	NR	\triangle	
1. Stove Top and Oven Gas Elect	Z					
2. Ventilator	ď			Ó		
3. Dishwasher				Z		
4. Disposal						
					Ш	
INTERIOR ACCESSORIES		_			^	
,	A	В	С	NR	Δ	
_	D					
,				D		
side				D		
2. Sliding door				1		

00

D

z a a a a a

ADDITIONAL COMMENTS:

see note: K Thimble

IMPORTANT INFORMATION PLEASE READ:

4. Stairway/Railings (Basement)

Stairway/Railings (Interior)

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Fireplaces are inspected visually only; test fires are not started as a part of this inspection. C. Check with current owner for location and condition of any and all screens and storm windows. D. Fog or condensation between insulated glass is an indication of a broken thermal seal. However, due to the nature of the defect this situation may not always be detected. E. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Damage beyond the tile surface is not accessible (NR) and further evaluation is suggested. Poor grouting will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members. F. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. G. Cosmetic defects such as: blemishes, worn carpets, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. H. Unless otherwise noted, all appliances are working on the day of the inspection. Tiger Home Inspection, inc. does not represent a guarantee or warranty of the continuous operation of the appliances. Self-cleaning mechanism, timers, clocks, thermostats, microwave ovens, clothes washing machines and dryers, and cosmetic blemishes are not part of this inspection report. I. Clean all grease vents and filters on a regular basis to prevent failure. J. Manufactured / pre-fab gas log units are not inspected as fireplaces but are considered space heaters. K. Solid fuel stoves are not inspected. If a solid fuel stove is present obtain a permit from the local building inspector or fire marshal prior to purchase. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions ca

@ GRIGINAL

Rust Cornsion AT Frame STALL



APARTMENT

TIGER HOME INSPECTION INC.®

HIRE THE EYE OF THE TIGER





Our rating system is as follows:

- Indicates item is functioning as originally intended.
- This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- Not inspected, not readily accessible or not present. No rating.
- Further consultation with a contractor is advised.

	Α_	В	С	NR	Δ	
Electric Service						()
Unit disconnect 135 AMP	Z					(12341)
Location /Circine						
2. Water Heater Type				D		
Size Manuf			_			
Thimble						
Staircase and handrail	1					
4. Door primary	3		0			
secondary						
	1			1		
5. Bath sink HW Temp \(\scrick{\scrick}{\scrick} \) *F	D D	4	4			
toilet	4	H		H		
	ADDODDDD	7				
	7	H	1	7	l	3 SKYLIGHT FOT WINDOW
3/4 ceiling Type Con		Z	ō	ō	N	
☐ Full ☐ window	1		ā			
floor Type Line Cun	Z,					
door	D					
🗹 🗭 /electric/fan						
heat source Temp°F		0000000000000	000000000000	0000000000		
baseboard/radiator/diffuser	1		_	Ф		
6. Room 610(26	N	00000000				
ceiling Type when the			1		M	DAMAGES BY WATER SCADIS
windows walls Type walls Type walls	4	H	4	4	NOR	
floor Type (Lase)	CACACA	H		مامومول	8	
door		7	d	3	1	
delectric outlets		ā	ā	ā	ā	
heat source Temp *F.	Z				ā	
d baseboard/adiator/diffusers	0					
7. Room (3<)						
ceiling Type wouldon's	8	7		H	7	I WASE DAMAGE AT WALL
II I code al acces	ā		Z	ă	Z	Jeillag Color
walls Type water sept	ā.		DOOD	000000	DVVO	Crisinal WINDOW
# floor Type	DAP					Citation Colorson
door	Z					
electric outlets	DOD!					
heat source Temp°F. baseboard/adiator/diffusers	4	H				
			-	4		
8. Room	13					
☐ ceiling Type	17)	ووومومو	4		9	
walls type		A	1	8	X	
floor Type		7	H	7	7	
door	ă	0	2	Z	ī	
electric outlets		0	7	/G		
heat source Temp°F.			0/	D	ā	
baseboard/radiator/diffusers			囟,	1		

IMPORTANT INFORMATION PLEASE READ:

A. The decision to upgrade electric service can be influenced by client need, local regulations and mortgage lending institutions. B. Once or twice a year flip the circuit breakers on and off to maintain good mechanical connections. C. Manufacturers' warranties for hot water heaters vary from manufacturer to manufacturer; this should not be confused with actual life expectancy which could be more or less. D. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. E. Depending on your individual needs, a tankless unit may not provide you with sufficient hot water. To increase quantity and efficiency you may wish to consider a booster tank or separate hot water heater. F. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. G. Check with the current owner for the location and condition of all screens and storm windows. H. Due to the nature of the deficiency, insulated windows and skylights may have broken thermal seals that may not be detected. I. We recommend all structures built prior to 1978 be tested for lead paint.

J. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Re-grouting of these cracks is a maintenance responsibility. Lack of maintenance will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members around tubs and showers. Plaster or sheetrock behind tile is not accessible. K. Cosmetic defects such as worn carpets, cracked floor tiles, fading or peeling paint, holes in walls, doors, ceiling and trim are not reported. L. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any con



HIRE THE EYE OF THE TIGER

7

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

BA	TI	1R	0	ON	1S
	~ E B		~	₩ 111	F 18 V

1. Bath sink HW Temp °F	
2. Bath sink HW Temp "F D D D D D D D D D	
3. Bath sink HW Temp °F	
4. Bath	

IMPORTANT INFORMATION PLEASE READ:

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Damage beyond the tile surface is not accessible (NR) and further evaluation is suggested. Poor grouting will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members around the tubs and showers. C. Check with current owner for location and condition of any and all screens and storm windows. D. Fog or condensation between insulated glass is an indication of a broken thermal seal. However, due to the nature of the defect this situation may not always be detected. E. Ground Fault Interrupter outlets or circuits are advised whenever the user will come in contact with water. F. Cosmetic blemishes or defects on floors, walls and cabinets are not reported. G. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any concerns. H. Radiant heat sources in slabs and ceilings are not accessible or tested.

HIRE THE EYE OF THE TIGER

8

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

INTERIORS

	A	В	С	NR	Δ	
Room		Ť	Ť	····		Luc uses on inspection
ceiling Type						The trops
windows		0		0	0	
☐ walls Type					0	
ifloor Type	A	0	0		la	
door		0	ā		la	
electric outlets			0		5	
,	F		0	0	5	
□ baseboard/radiator/diffusers . /					6	
Room	-	-			_	
ceiling Type						
windows						
walls Type						
floorType						
door						N.
electric outlets/		0				
heat source temp						
☐ baseboard/radiator/diffusers						
Room/						
ceiling Type						
□ windows	. 0					
walls fype		0				
floor/Type						
□ door/	. 0					
electric outlets	. 🔾					
heat source Temp						
baseboard/radiator/diffusers	. 🗆					
Room	-					
🖵 ceiljng Type						
windows						
walls Type						
oorType						
□ /door						
electric outlets						
heat source Temp	_					
baseboard/radiator/diffusers	. 0					

IMPORTANT INFORMATION PLEASE READ:

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Fireplaces are inspected visually only, test fires are not started as part of this inspection. If applicable, obtain a permit from the local building inspector or fire marshal before operating any solid fuel stoves. C. Check with current owner for location and condition of any and all screens and storm windows. D. Due to the nature of the deficiency, insulated windows and skylights may have broken thermal seals that may not be detected. E. We recommend all structures built prior to 1978 be tested for lead paint. F. Cosmetic defects such as: worn or torn carpets, fading or peeling paint, holes, in walls, doors, ceiling and trim are not reported. G. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any concerns. H. Radiant heat sources in slabs and ceilings are not accessible or tested.



HIRE THE EYE OF THE TIGER

9

Our rating system is as follows:

- A: Indicates item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade, is required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade, is required.
- NR: Not inspected, not readily accessible (NA) or not present (NP). No rating.
- △: Further consultation with a contractor is advised.

ATTIC VENTILATION / INSULATION

		Α.	В	С	NR	Δ	
١.	Access to attic	A	å	ā	Z		_ NO DITTIC
1.		4	u	4	Д	اا	- W 131(1C
	□ scuttle □ stairs						
	pull down						
	How viewed						
	Flooring Yes No						
-	Attic Lighting Yes No				١,		
2.	Structural supports				Z		
	☐ rafter Type						
	post & beam collar tie truss						
3.	Roof backings				Ø		
	☐ wood ☐ OSB						
	☐ plywood						
4.	Ceiling joist Type				1		
5.	Flashing				Z		
	☐ vent pipes ☐ valleys						
	☐ chimneys ☐ flashing sealer						
6.	Chimney (flue liner not included)				1		
7.	Insulation/vapor barrier (attic only)				Ø		
	☐ fiberglass ☐ cellulose						
	☐ mineral wood ☐ vermiculite						
	□ other						
	Depth						
8.	Ventilation Type				1		
9.	Duct work (in attic)						
	☐ galv. steel ☐ alum. ☐ flexiduct ☐ other		_		_		
10.	Whole house fan						
11.	Evidence of water penetration				6		
	See Note: E						\
	■ No visible or accessible evidence at the time of inspection						
	 Evidence of prior water penetration. Consult with owner or monitor for source and repair. 						
	☐ Active water penetration						


ADDITIONAL COMMENTS:

IMPORTANT INFORMATION PLEASE READ:

A. The home buyer should be aware that prior to the adoption of federal, state and local codes in the mid 70's, homes were typically built with minimum insulation. Today's home buyer, faced with rising energy costs, should consider the return on investment of insulation upgrades. B. Attic ventilation is an important factor in the life expectancy of roof sheathing and shingles. Provide maximum air flow to minimize heat buildup in summer and condensation in winter. Do not cover or block vents. C. All flashing should be inspected and be repaired when needed. D. Tarred flashing points indicate a repair of sealing of original flashing. The tar composition has a limited life expectancy and therefore future re-application or repair will be required. E. Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any concerns.

HIRE THE EYE OF THE TIGER 1-800-62-TIGER

www.tigerhomeinspection.com



INSECT DAMAGE DISCLOSURE

X =

Storage

Suspending Ceiling

Finish

This report DOES NOT WARRANTY the absence of wood-boring insects. It is only a visual examination of the readily accessible areas. The inspection report is intended to record evidence or activity found on the day of an inspection.

Sills

Girder

Wood Trim

S =

W

=

Our inspectors rely solely on visual, nondestructive methods when performing their inspection. We do not remove or disturb areas such as walls, insulation, paneling, or baseboards, fixed materials, permanent or non-permanent ceiling tiles when performing a wood-boring insect inspection. Repairs and renovations to a home or other changes in conditions may reveal insect activity that was not discoverable during an inspection. If evidence of wood-boring insect activity has been removed or concealed before the inspection, even a trained expert will not be able to detect the presence of wood-boring insects.

Our inspections are based on observations that would indicate past or present infestations, not future activity. Consequently, there is always a risk of insect activity that is not discoverable during an inspection. For your protection, you should consult a licensed pest control company for a complete wood destroying insect inspection and about any warranties commonly available to protect you in case of future insect activity.

REVISED JULY 2008 COPYRIGHT PENDING

=

=

M

Ants

Mud Tubes

Previous Treatment

Wood Destroying Insect Inspection Report	Notice: Please read imp	ortant consum	ner information on page 2.		
Section I. General Information Inspection Company, Address & Phone	Company's Business L		Date of Inspection		
Tiger Home Inspections, Inc. 969 Washington Street Braintree, MA 02184 1-800-62 TIGER	Address of Property Inspected CO NUCLOW ST BUSTON MD				
Inspector's Name, Signature & Certification, Registration, or Lic. # 32233	U(C# 68	Structure(s)	Inspected		
Merinoneill 1 fames Authorize	d Rep. for J.E. Rizzo Jr.		WALLE		
Section II. Inspection Findings This report is indicative of the condection be construed as a guarantee or warranty against latent, concealed, or future readily accessible areas of the structure(s) inspected. A. No visible evidence of wood destroying insects was observed. B. Visible evidence of wood destroying insects was observed as formula in the concept of the condection of the cond	re infestations or defects.	Based on a d	careful visual inspection of the		
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or s	taining (description and	ocation):			
3. Visible damage from wood destroying insects was noted as	follows (description and	location):	5949 3 10 10 10 10 10 10 10 10 10 10 10 10 10		
NOTE: This is not a structural damage report. If box B above including hidden damage, may be present. If any questions arise regar interested parties contact a qualified structural professional to determine Yes No It appears that the structure(s) or a portion thereof may have the inspecting company can give no assurances with regard to work dor contacted for information on treatment and any warranty or service agreem	ding damage indicated by the extent of damage an nave been previously trea ne by other companies. T	y this report, it d the need for ated. Visible ev he company the	is recommended that the buyer or any repairs.		
Section III. Recommendations No treatment recommended: (Explain if Box B in Section II is checked)	i)		Commence with the Commence		
Recommend treatment for the control of:		and Sales	izeronen ega zenimerado		
Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed or inaccessible Areas	ccessible:	1	The inspector may write out obstructions or use the following optional key: 1. Fixed ceiling 13. Only visual access		
Crawlspace		3	2. Suspended ceiling 14. Cluttered condition 15. Standing water		
☐ Main Level Attic			4. Floor covering 16. Dense vegetation 5. Insulation 17. Exterior siding		
☐ Affic ———————————————————————————————————		6	6. Cabinets or shelving 18. Window well covers		
Exterior		1	7. Stored items 19. Wood pile 3. Furnishings 20. Snow		
Porch		9	Appliances 21. Unsafe conditions		
Addition		1	10. No access or entry 22. Rigid foam board 11. Limited access 23. Synthetic stucco 24. Duct work, plumbing,		
Section V. Additional Comments and Attachments (these a	ure an integral part of the	report)	and/or wiring.		
The state of the s			to upon blunda urcer mon		
Attachments					
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.	receipt of a copy of understands the info	both page 1 a	dersigned hereby acknowledges nd page 2 of this report and ted.		
X	XX				

Form NPMA-33 (9/01/04) © 2004 National Pest Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA. Tiger Home Inspection, Inc. has been granted permission to reproduce this form through 01/31/09.

Important Consumer Information Regarding the Scope and Limitations of the Inspection.

Please read this entire page as it is part of this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- Treatment Recommendation Guidelines Regarding Subterranean Termites: FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites - but no activity - are found in a structure that shows no evidence of having been treated for subterranean termites in the past, then a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence of subterranean termites - but no activity - if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a licensed pest control company.
- Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.